



ODISHA FIRE & EMERGENCY SERVICE

FIRE SAFETY CERTIFICATE

FORM-V

[Under rule-13(3) of the Odisha Fire Prevention and Fire Safety Rules, 2017]

Certificate No:	FIRCER1409280082025006851	Application No:	FSC1409280082025000001
Date of Issue:	26-07-2025	Date of Receipt of Application:	23-07-2025
Valid Up to:	25-07-2027 (midnight)		
(Apply for Renewal of Fire Safety Certificate at least three months before its expiry)			

Certified that the

Aditya Birla Public School, Osapada,
Rayagada

Situated at

Plot No-501, 502, 503, 504, 505, 506 and 942/1182, Khata No.-186/1, Street-Tikiri
Road, Mouza-Osapada, Police Station-Tikiri, District-Rayagada, Fire Station-Kasipur,

Consisting of total

1 Number of Towers/Blocks, was
inspected by officers of the Fire Service
on

26-07-2025

In presence of

Abhay Kumar Srivastava, Assistant
Manager and other staffs.

and it has been found to comply with the fire prevention and safety requirements in accordance with the Odisha Fire Prevention and Fire Safety Rules, 2017 read with Odisha Fire Prevention and Fire Safety(Amendment) Rules,2019 and that its various floors are fit for occupancy or usage as noted hereunder against each subject to compliance to the conditions as prescribed herein below:

1. * Name of the Building(s)/Tower(s)/Block(s):- Aditya Birla Public School

* Floor wise occupancy:-


PRINCIPAL
ADITYA BIRLA PUBLIC SCHOOL
OSAPADA, RAYAGADA
CBSE Aff. No-1530186
School No-15278



Sl.No.	Floors in Tower/Block	Usage
1	Basement -	L. house keeping room, G. housekeeping room & Indoor sport room
2	Ground Floor -	Class room-13 Nos, staff room, teachers room, principal room, vice principal room, medical room, meeting room, conference room, admin room, junior computer lab, junior science room, examination store, parents room, electrical room, server room, library & Auditorium
3	First Floor -	Class room-17 Nos, store room, art room, bio lab, chem. Lab, phy lab, senior com lab, geography lab, electrical room & A.V room

CONDITIONS:-

1. Fire prevention and safety measures and appliances, availability of water supplies and means of access thereto etc provided in the building or premises, should be maintained by the occupier(s) in best repairs and efficient working condition at all times for use by the occupants or the members of the Fire Service or both in the event of outbreak of fire.
2. The set-backs, driveways, entrance gates, exits, staircases, corridors and escape way should not be changed, obstructed or modified in any way.
3. The occupiers(s) shall train all staff and occupants periodically to make them well conversant in use and operation of the fire prevention and safety measures.
4. Fire drills/rehearsals should be organised at least once in six months by involving Local Fire Station.
5. Photocopies of this Certificate should be framed and displayed at all conspicuous places in all lobbies/corridors in all floors of all Towers/Blocks of building/premises.
6. The maintenance of fire safety installation in the building / premise shall be owner's / occupier's liability as per Rule-16 of OFP & FS Rules, 2017. He shall maintain the same in good repairs and working condition at all times. Any lapses in fire safety installation during fire incident if any shall end with owner's / occupier's responsibility.

By order of the Director of Fire Service

Birabhadra Tudu

Deputy Fire Officer, Koraput Circle

NOTE

- (i) It is a digitally signed electronically generated certificate and therefore needs no ink-signed signature.
- (ii) This Certificate is issued as per section 4, 5, & 6 of Information Technology Act 2000 and its subsequent amendments in 2008.
- (iii) For any Query or Verification, Agency / Department / Office may visit <https://agnishamaseva.odisha.gov.in>
- (iv) Tampering of this Certificate will attract penal action.

PRINCIPAL
ADITYA BIRLA PUBLIC SCHOOL
OSAPADA, RAYAGADA
CBSE Aff. No-1530186
School No-15278

