


**BUILDING SAFETY CERTIFICATE OF : THE ADITYA BIRLA PUBLIC SCHOOL,
GADCHANDUR**

Certified that the School Building of The Aditya Birla Public School, Gadchandur has been inspected by me on dated 01.03.2024 and school building structure is found R C C framed with RCC footing, column, beam and slab. The structurally building is fit and safe. This certificate is issued as per request from The Principal, The Aditya Birla Public School, Gadchandur vide letter no. ABPS/out/2024 dated 24.02.2024.


(Shubham Adetiwar)
Asst. Executive Engineer
Public Works Sub-Division
Gadchandur



(S.V. Kumbhe)
Executive Engineer
Public Works Division No. 1
Chandrapur


Outward No. 16091.../D-1/Fit./Cert./2024

Dated : 11.03.2024

Copy forwarded to:

1. The Principal, The Aditya Birla Public School, Gadchandur. For favors of information.
2. Asst. Executive Engineer, Public Works Sub-Division, Gadchandur for information.