

Stability Certificate

This is to certify that the The Aditya Birla Public School Kharach Ta.Hansot going to Utilized School Building and I am of the opinion that the School Building of the said premises appears in sound condition based on report by Structural Engineer BAUDA Gunjan Vekaria M.E.(Structure), B.E.(Civil), AMIE, Chartered Engineer Registration No Bauda-Lic No. 1122SE1507291028 (Structure Engineer) (Grade 1) Bharuch, comments of said school Building Ground Floor, First Floor at Old survey no. 240 & 250 Kharach Ta.Hansot having RCC Frame Structure Ground + One Storey Building is structurally safe and stability will not be endangered for the continued use for which the building was intended.

This Certificate valid only for one year.

Place : Ankleshwar

Date : 19/05/2026



Deputy Executive Engineer
R & B Sub Division
Ankleshwar

